

S-340
Cedar Lane Farm
Princess Anne vicinity
private

c. 1870

Cedar Lane farm is located on the east side of the old Princess Anne-Westover Road south of Princess Anne. The nineteenth-century cross gabled farmhouse is accompanied by a group of contemporary outbuildings. A concrete ribbed silo stands near a granary and two corn cribs. The winding entrance lane is bordered by a mature row of cedars.

Maryland Historical Trust State Historic Sites Inventory Form

Survey No. S-340

Magi No. 2003405535

DOE ☐ yes ☐ no

1. Name (indicate preferred name)

historic

and/or common Cedar Lane Farm

2. Location

street & number East side of Old Princess Anne - Westover Road ☐ not for publication

city, town Princess Anne ☒ vicinity of congressional district First

state Maryland county Somerset

3. Classification

| Category | Ownership | Status | Present Use |
|---|--|---|---|
| <input checked="" type="checkbox"/> district | <input type="checkbox"/> public | <input checked="" type="checkbox"/> occupied | <input type="checkbox"/> agriculture |
| <input checked="" type="checkbox"/> building(s) | <input checked="" type="checkbox"/> private | <input type="checkbox"/> unoccupied | <input type="checkbox"/> commercial |
| <input type="checkbox"/> structure | <input type="checkbox"/> both | <input type="checkbox"/> work in progress | <input type="checkbox"/> educational |
| <input type="checkbox"/> site | Public Acquisition | Accessible | <input type="checkbox"/> entertainment |
| <input type="checkbox"/> object | <input type="checkbox"/> in process | <input checked="" type="checkbox"/> yes: restricted | <input type="checkbox"/> government |
| | <input type="checkbox"/> being considered | <input type="checkbox"/> yes: unrestricted | <input type="checkbox"/> industrial |
| | <input checked="" type="checkbox"/> not applicable | <input type="checkbox"/> no | <input type="checkbox"/> military |
| | | | <input type="checkbox"/> museum |
| | | | <input type="checkbox"/> park |
| | | | <input checked="" type="checkbox"/> private residence |
| | | | <input type="checkbox"/> religious |
| | | | <input type="checkbox"/> scientific |
| | | | <input type="checkbox"/> transportation |
| | | | <input type="checkbox"/> other: |

4. Owner of Property (give names and mailing addresses of all owners)

name Morton

street & number Cedar Lane Farm telephone no.:

city, town Princess Anne state and zip code Md. 21853

5. Location of Legal Description

courthouse, registry of deeds, etc. Somerset Clerk of Court liber

street & number Somerset County Courthouse folio

city, town Princess Anne state Md. 21853

6. Representation in Existing Historical Surveys

title

date ☐ federal ☐ state ☐ county ☐ local

depository for survey records

city, town state

7. Description

Survey No. S-340

| | | | | |
|--|---------------------------------------|---|---|--------------------|
| Condition | | Check one | Check one | |
| <input type="checkbox"/> excellent | <input type="checkbox"/> deteriorated | <input type="checkbox"/> unaltered | <input checked="" type="checkbox"/> original site | |
| <input checked="" type="checkbox"/> good | <input type="checkbox"/> ruins | <input checked="" type="checkbox"/> altered | <input type="checkbox"/> moved | date of move _____ |
| <input type="checkbox"/> fair | <input type="checkbox"/> unexposed | | | |

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Cedar Lane Farm description

Cedar Lane Farm is located on the east side of the old Princess Anne-Westover Road three miles south of Princess Anne, Somerset County, Maryland. The two-story, three-bay farmhouse faces west with the principal gable oriented on a north/south axis. Accompanying the house is a small group of nineteenth and twentieth-century outbuildings.

Standing at the end of a long farm lane bordered by mature cedar trees is a third quarter of the nineteenth-century frame farmhouse that is supported by a brick pier foundation and is sheathed with aluminum siding. The steeply pitched roof has extended eaves and an exterior layer of asphalt shingles. Attached to the back of the house is a two-story, two-bay service wing.

The west (main) elevation is a symmetrical three-bay facade with a center entrance and flanking single pane sash windows with alumin shutters. Stretching across the first floor front is a single-story porch that wraps around the north side. The second floor is lighted by three single pane sash windows, and a cross gabled is marked by a pointed arch attic light. Piercing the roof is a pair of narrow brick stove stacks.

The south gable end has a paired single-pane sash window on the first floor and a single sash window on the second floor.

The rear elevation is partially covered by a two-story, two-bay ell service wing supported by a partially excavated cellar. The exterior finishes remain consistent with the main house, and central interior brick stack rises through the roof. Attached to the east end of the service wing is a single-story garage.

The interior of the house was not surveyed.

Positioned directly behind the house is a group of farm buildings including a conical silo, a granary, two corn cribs, and an outbuilding of undetermined use. The largest frame structure is the frame granary which is supported by a brick pier foundation and is sheathed by plain weatherboards. A steeply pitched gable front roof covers the center section, and a shed roof covers the flanking side rooms. Three board doors provide access to the three ground level spaces, and a smaller door opens into the loft. Flanking the granary are two corn cribs with flanking wagon bays. Both structures are supported by brick pier foundations. The north crib is covered by a continuous gable roof, whereas the south crib has a broken roofline. Located north of the crib is the round silo constructed of ribbed concrete and stabilized by metal rings. The silo is capped by conical roof. North of the house is a two-room frame outbuilding of undetermined use. Two front doors open into separate cells, and the east door has long strap hinges. The frame is covered with weatherboard siding, and the roof retains a deteriorated layer of wood shingles.

8. Significance

Survey No. S-340

| Period | Areas of Significance—Check and justify below | | | |
|---|--|---|---|--|
| <input type="checkbox"/> prehistoric | <input type="checkbox"/> archeology-prehistoric | <input type="checkbox"/> community planning | <input type="checkbox"/> landscape architecture | <input type="checkbox"/> religion |
| <input type="checkbox"/> 1400–1499 | <input type="checkbox"/> archeology-historic | <input type="checkbox"/> conservation | <input type="checkbox"/> law | <input type="checkbox"/> science |
| <input type="checkbox"/> 1500–1599 | <input type="checkbox"/> agriculture | <input type="checkbox"/> economics | <input type="checkbox"/> literature | <input type="checkbox"/> sculpture |
| <input type="checkbox"/> 1600–1699 | <input checked="" type="checkbox"/> architecture | <input type="checkbox"/> education | <input type="checkbox"/> military | <input type="checkbox"/> social/ |
| <input type="checkbox"/> 1700–1799 | <input type="checkbox"/> art | <input type="checkbox"/> engineering | <input type="checkbox"/> music | <input type="checkbox"/> humanitarian |
| <input checked="" type="checkbox"/> 1800–1899 | <input type="checkbox"/> commerce | <input type="checkbox"/> exploration/settlement | <input type="checkbox"/> philosophy | <input type="checkbox"/> theater |
| <input type="checkbox"/> 1900– | <input type="checkbox"/> communications | <input type="checkbox"/> industry | <input type="checkbox"/> politics/government | <input type="checkbox"/> transportation |
| | | <input type="checkbox"/> invention | | <input type="checkbox"/> other (specify) |

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☐ C ☐ D
and/or


Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

SIGNIFICANCE

Cedar Lane Farm is a marginally significant group of nineteenth-century farm buildings. Third quarter of the nineteenth-century farmhouse has been extensively reworked with artificial layers of siding and modern sash windows. The granary, corn cribs, and silo are not uncommon farm buildings for the area.



SCALE 1:24 000

1 MILE

1 KILOMETER

The graphic scale bars show distances in feet (0 to 7000) and kilometers (0 to 1). The scale is 1:24,000.



MARYLAND

QUADRANGLE

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS
FOR SALE BY U. S. GEOLOGICAL SURVEY, RESTON, VIRGINIA 22092
A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST



Cedar Lane Farm


S-340

Princess Anne vicinity, Somerset Co., MD

South Elevation

10/85, Paul Touart, Photographer

Neg./MD Hist. Trust



Cedar Lane Farm S-340
Princess Anne vicinity, Somerset Co., MD
Outbuilding
10/85, Paul Touart, Photographer
Neg./MD Hist. Trust



Cedar Lane Farm S-340
Princess Anne vicinity, Somerset Co., MD
Granary and corn crib
10/85, Paul Touart, Photographer
Neg./MD Hist. Trust



Cedar Lane Farm

S-340

Princess Anne vicinity, Somerset Co., MD

Granary and corn crib

10/85, Paul Touart, Photographer

Neg./MD Hist. Trust



Cedar Lane Farm

S-340

Princess Anne vicinity, Somerset Co., MD

Silo

10/85, Paul Touart, Photographer

Neg./MD Hist Trust